

# About the firmware version 2.78 update

Last Modified: February 2nd, 2024

## What's included in 2.78 (changes since 2.76)?

### Fixes and improvements:

- Support for PDUs with 12 branches.
- Support for 63A PDUs.
- Fix for branch voltage drop alert.

### Notes:

- Recommended version for most users.
- Since SPDM version 2.70 multiple Branch and Total registers are moved to a higher register-range 21000-24054. This means that all PDUs on the data bus must have the same firmware version as the bridge PDU to stay compatible. If a bridge PDU is version 2.70 or newer, versions higher than 2.62 but lower than 2.70 are not supported on the data bus, this works also the other way around.

## Installing this firmware

### Installing this firmware

Installation of firmware is preferred by using the Conteg Tool (SPST version 1.4.8). There is a specific SPST user manual available on the CONTEG website.

### Notes:

- While updating or restarting the devices, power distribution will not be interrupted.



CONTEG, spol. s r.o.

Štětkova 1638/18, 140 00 Prague 4, Czech Republic

Tel: +420 261 219 182, E-mail: [conteg@conteg.cz](mailto:conteg@conteg.cz), Web: [www.conteg.cz](http://www.conteg.cz)

Identification No.: 257 018 43, VAT: CZ 257 018 43