

# Firmware changelog

## RAMOS Optima

*Latest FW version: SP8474*

### *Table of added and fixed features*

#### **2017-09-21 Version SP8474**

- Add: Support for the new design dual Temperature/Humidity sensor

#### **2014-05-09 Version SP8468**

- Fix: Dry contacts syslog shows sensor is overvoltage.

#### **2014-04-11 Version SP8467**

- Fix: The cycle relay duration is not functioning for long durations

#### **2014-02-10 Version SP8465**

- Fix: When password checking is disabled the SNMP community is not verified.
- Fix: Changing the threshold value of temperature does not send SNMP traps.
- Fix: Relay action wording "until Ack" does not show in drop down list.
- Fix: When the humidity is 0%, the sensor shows sensor error (We added a 5% margin before setting the sensor error state)