About the firmware version 2.62 update

Last Modified: October 9th, 2020

What's included in 2.62 (changes since 2.60)?

New features:
- Added choice of dhcp hostname: serial number or sysname
- Added locate function that blinks display at request
- Added devicetype readout (sdbDevIdDeviceType)

Fixes and improvements:
- Improved firmware update handling
- Improved usb detection and device handling
- Fixes extraneous sensor change alerts
- Miscellaneous minor improvements and fixes
- Fixed SNMP V3 encryption issues
- Fixed SNMP-trap temperature alert (specific-trap)
- Updated German language items
- Fixed deactivating usernames
- Fixed ip ranges for blocking access
- Fixed unit address field length
- Optimization of TLS/HTTPS and fixed related issues
- General performance and stability improvements

Notes:
- Updated MIB files

Installing this firmware

Installation of firmware is preferred by using the CONTEG Product Service Tool (SPST version 1.1.8). There is a specific SPST user manual available on the Schleifenbauer website.

Notes:
- Uploading 2.xx bin files in the Gateway's web interface is not possible!
- While updating or restarting the devices, power distribution will not be interrupted.