

# About the firmware version 2.68 update

Last Modified: October 4th, 2022

## What's included in 2.68 (changes since 2.66)?

### New features:

- Introducing hardware support for updated outlet switching circuits.

### Fixes and improvements:

- –

### Notes:

- -

## Installing this firmware

Installation of firmware is preferred by using the CONTEG Product Service Tool (SPST version 1.4.3). There is a specific SPST user manual available on the Schleifenbauer website.

### Notes:

- While updating or restarting the devices, power distribution will not be interrupted.



CONTEG, spol. s r.o.  
Štětkova 1638/18, 140 00 Prague 4, Czech Republic  
Tel: +420 261 219 182, E-mail: [conteg@conteg.cz](mailto:conteg@conteg.cz), Web: [www.conteg.cz](http://www.conteg.cz)  
Identification No.: 257 018 43, VAT: CZ 257 018 43