

About the firmware version 2.70 update

Last Modified: January 15th, 2023

What's included in 2.70 (changes since 2.68)?

New features:

- Fast switching option to quickly switch multiple outlets in the web interface
- New SNMP registers available (outlet unlock override)

Fixes and improvements:

- Fixed Modbus register mapping of registers added since 2.64
- Fixed outlet switching issue in some cases
- Improved https security and initial sequence numbers

Notes:

- Recommended version for most users

Installing this firmware

Installation of firmware is preferred by using the CONTEG Product Service Tool (SPST version 1.4.4). There is a specific SPST user manual available on the CONTEG website.

Notes:

- While updating or restarting the devices, power distribution will not be interrupted.

