

# About the SPST version 1.4.8 update

Last Modified: February 2nd, 2024

## Minimum requirements:

Windows OS	Mac OS	Linux OS
Windows 7 or higher	10.15 or higher	Ubuntu 18 or higher

## What's included in 1.4.8 (changes since 1.4.7)?

This version of SPST contains PDU firmware version 2.78 PL3228 as well as a few general improvements.

## New features:

- The latest firmware, 2.78 PL3228, for Schleifenbauer PDUs has been added to SPST.

## Fixes:

- Ping during firmware upgrade fix



CONTEG, spol. s r.o.  
Štětkova 1638/18, 140 00 Prague 4, Czech Republic  
Tel: +420 261 219 182, E-mail: [conteg@conteg.cz](mailto:conteg@conteg.cz), Web: [www.conteg.cz](http://www.conteg.cz)  
Identification No.: 257 018 43, VAT: CZ 257 018 43