

About the SPST version 1.4.7 update

Last Modified: October, 23rd, 2023

Minimum requirements:

Windows OS	Mac OS	Linux OS
Windows 7 or higher	10.15 or higher	Ubuntu 18 or higher

What's included in 1.4.7 (changes since 1.4.6)?

This version of SPST contains PDU firmware version 2.76 PL3213 as well as a few general improvements.

New features:

- The latest firmware, 2.76 PL3213, for CONTEG PDUs has been added to SPST.
- Enlarged Discovery login field.
- IPv6 support.
- Internal register model is synchronized with the latest SPDM version.
- Connects with WEBAPI and IPAPI through Basic Authentication if available.

Fixes:

- Fix for writing username and password to a PDU.
- Fix for Linux where SPST would not launch because of Wayland.
- Fix for an internal comparison of firmware build numbers.
- Firmware updating is made more robust. The reboot command could in rare instances arrive at a point in time when the PDU could not process it. This is fixed and should improve firmware update success rate.



CONTEG, spol. s r.o.
Štětškova 1638/18, 140 00 Prague 4, Czech Republic
Tel: +420 261 219 182, E-mail: conteg@conteg.cz, Web: www.conteg.cz
Identification No.: 257 018 43 , VAT: CZ 257 018 43